


Monday 2nd April 2018

Appendix 5:



- DP = Decking Panel Missing Above Walkway
- BC = Beam Safety Clip Missing
- TW = Upright Slight Twist
- ExB = Extra Beam level Fitted
- HB = Horizontal Brace Slight Damage
- FB = Front Beam Slight Damage

